




## Z-axis controlled milling



- tolerances in z-axis  $\pm 9 \mu\text{m}$
- can replace laser work
- cost saving process compared to laser process

